

Message

---

**From:** Spurlin, Steve [/O=EXCHANGELABS/OU=EXCHANGE ADMINISTRATIVE GROUP (FYDIBOHF23SPDLT)/CN=RECIPIENTS/CN=7AE2616803EE42B9B9F19A2B12FCE89F-SPURLIN, STEVE]  
**Sent:** 4/14/2019 3:48:11 PM  
**To:** Moore, Tony [moore.tony@epa.gov]  
**CC:** Webster, James [Webster.James@epa.gov]; Jardine, Rick [Jardine.Richard@epa.gov]  
**Subject:** Pipeline update

I demobed yesterday but plan to return Monday for a coordination meeting with Colonial and Tdec. I'm also continuing monitoring of site using my local START. Colonial is demobing their IMT today put leaving their response resources. Colonial is drafting an O & M plan for foreseeable future. I will see what comes from Monday meeting. TDEC often noncommittal on issues.

If they have a good O & M plan, is that our path out? It's likely there will be periodic sheening on water for some unknown period but their collection trench and other measures seem to be minimizing the discharge. No visible sheen observed off airport property.

Sent from my iPhone